



Photograph 1. View of unpermitted fill/berm on Brown property (looking north). Old Hollister Street Bridge at right.



Photograph 2. View showing unpermitted fill/berm on property (looking south). Note *Arundo donax* in background, along existing river channel.



Photograph 3. View along unpermitted fill/berm (looking west). Tijuana River to left (south). *Arundo donax* infestation visible in background.



Photograph 4. View west along unpermitted fill/berm.



Photograph 5. Unpermitted fill/berm, looking south along Old Hollister Street Bridge.



Photograph 6. Old Hollister Street Bridge (looking southeast) showing non-native vegetation (*Arundo donax*) in background.