Flooding in and adjacent to balloon track caused by balloon track.

(Looking southeast from Glenshire Drive)





SWANSON HYDROLOGY + GEOMORPHOLOGY
500 Seabright Ave, Suite 202 Santa Cruz, CA 95062
PH 831.427.0288 FX 831.427.0472

FIGURE 13: Reach 4 channel and habitat conditions.

SWANSON HYDROLOGY + GEOMORPHOLOGY
500 Seabright Ave, Suite 202 Santa Cruz, CA 95062
PH 831.427.0288 FX 831.427.0472

FIGURE 14: Reach 5 channel and habitat conditions.

Flooding in and adjacent to balloon track.

(Looking west from end of balloon track retaining wall)



Flooding in and adjacent to balloon track near lumber yard.

(Looking southwest from Hwy 267)