
Landslide
Active
Inactive
Ancient
Landslide Feature
Bank Erosion
3 5' or greater
2 2' to 5'
1 .5' to 2'
0 less than .5'
1,800 900 0 1,800 3,600 5,400 7,200
Feet
STATE OF CALIFORNIA
DEPARTMENT OF WATER RESOURCES
Oroville Facilities Relicensing
FERC Project No. 2100
N
Appendix C
Plate B
Landslide and
Shoreline Erosion Map
of Lake Oroville Area
Prepared by:
AMG DWR Northern District
Date
2/08/03
ND109 - D:/projects/ferc_geology/
bank_erosion_landslides/
bankerosion_landslides.mxd