



U.S. ARMY CORPS
OF ENGINEERS

SUTTER BYPASS Fact Sheet

PL84-99 Sites

Emergency Levee Repairs

Location

Watercourse: Sutter Bypass

Site Identification #:
20051230-019-001
(Levee Mile 0.55)

Latitude/Longitude:
39.142528/-121.841250

Nearest Impact Area:
Meridian

County: Sutter

Bank: Right

Type of Damage

Bank erosion

Total Length of Repair

150 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

Reclamation District 70



For further information, please contact:

Les Schmittner
Project Manager
U.S. Army Corps of Engineers
(916) 440-2263

Lester.C.Schmittner@spk01.usace.army.mil

