

Problems that continue to arise.

- STILL no enforcement at the city level
- The interpretation of the PRESCRIPTIVE is out of control. Some cities have taken the 2500 sf threshold to 5000 sf
- City inspectors do not know what they are looking at and are signing off on projects that do not comply (developers are leaning on cities to turn a blind eye to NON compliant installations)
- Extremely poor design for the prescriptive measure.
- o No irrigation design, no MAWA calcs, irrigation equipment being installed does not meet the MWELo standards etc etc.
- o Prescriptive should require an INSPECTION by an EPA certified auditor (an audit really isn't necessary)
- Cities are allowing LOW FLOW overhead irrigation in mulched planting areas and in areas less than 10' wide.

Andrew Bolt