DEPARTMENT OF
WATER RESOURCES

BUTTE CREEK Fact Sheet

PL84-99 Sites

Emergency Levee Repairs

Location

River: Butte Creek
Site Identification #:
20051230-034-002
(Levee Mile 0.8)
Latitude/Longitude:
39.691261/-121.774594
Nearest Impact Area:
Agricultural/Residential
County: Butte
Bank: Left

Type of Damage

Bank erosion

Total Length of Repair

40 feet (approximate)

Repair Type

Rock slope protection,
rock-soil fill

Lead Agency

Maintenance Area 5

For further information, please contact:

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov