



DEPARTMENT OF  
WATER RESOURCES

# SACRAMENTO BYPASS *Fact Sheet*

PL84-99 Sites

## Emergency Levee Repairs

### Location

River: Sacramento Bypass  
Site Identification #:  
20051230-037-003  
(Levee Mile 1.4)  
Latitude/Longitude:  
38.59525/-121.58463  
Nearest Impact Area:  
Agricultural  
County: Yolo  
Bank: Left (South Levee)

### Type of Damage

Sloughing

### Total Length of Repair


75 feet (approximate)

### Repair Type

Compacted fill/geotextile

### Lead Agency

Department of Water Resources,  
Sutter Maintenance Yard



**For further information,  
please contact:**

**Elizabeth Scott**  
**DWR Public Affairs Office**  
**(916) 835-5344**  
**leveerepair@water.ca.gov**

DEPARTMENT OF WATER RESOURCES  
PO Box 942836, Sacramento, CA 94236

**www levees.water.ca.gov**