



DEPARTMENT OF
WATER RESOURCES

SACRAMENTO BYPASS *Fact Sheet*

PL84-99 Sites

Emergency Levee Repairs

Location

River: Sacramento Bypass

Site Identification #:
20051230-037-004
(Levee Mile 1.7)

Latitude/Longitude:
38.595717/-121.582933

Nearest Impact Area:
West Sacramento

County: Yolo

Bank: Left (South Levee)

Type of Damage

Sloughing

Total Length of Repair


75 feet (approximate)

Repair Type

Compacted fill/geotextile

Lead Agency

Department of Water Resources,
Sutter Maintenance Yard



For further information,
please contact:

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www levees.water.ca.gov