



DEPARTMENT OF  
WATER RESOURCES

# SACRAMENTO RIVER Fact Sheet

PL84-99 Sites

## Emergency Levee Repairs

### Location

River: Sacramento  
 Site Identification #:  
 20051230-039-002  
 (River Mile 10.9)  
 Latitude/Longitude:  
 38.137267/-121.686474  
 Nearest Impact Area:  
 Brannan-Andrus Island  
 County: Sacramento  
 Bank: Left

### Type of Damage

Bank scour

### Total Length of Repair


100 feet (approximate)

### Repair Type

Rock fill, rock-soil mix,  
 rock slope protection

### Lead Agency

Brannan-Andrus Levee  
 Maintenance District



For further information,  
 please contact:

**Elizabeth Scott**  
 DWR Public Affairs Office  
 (916) 835-5344  
 leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES  
 PO Box 942836, Sacramento, CA 94236

[www levees.water.ca.gov](http://www levees.water.ca.gov)

