



DEPARTMENT OF  
WATER RESOURCES

# SACRAMENTO RIVER Fact Sheet

PL84-99 Sites

## Emergency Levee Repairs

### Location

River: Sacramento

Site Identification #:  
20051230-039-004  
(River Mile 11.2)

Latitude/Longitude:  
38.156000/-121.680067

Nearest Impact Area:  
Brannan-Andrus Island

County: Sacramento

Bank: Left

### Type of Damage

Bank scour

### Total Length of Repair


85 feet (approximate)

### Repair Type

Rock fill, rock-soil mix,  
rock slope protection

### Lead Agency

Brannan-Andrus Levee  
Maintenance District



For further information,  
please contact:

**Elizabeth Scott**  
DWR Public Affairs Office  
(916) 835-5344  
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES  
PO Box 942836, Sacramento, CA 94236

[www.levees.water.ca.gov](http://www.levees.water.ca.gov)

