



## Emergency Levee Repairs

### Location

River: Sacramento  
Site Identification #:  
20051230-039-008  
(River Mile 12.8)  
Latitude/Longitude:  
38.158317/-121.677017  
Nearest Impact Area:  
Brannan-Andrus Island  
County: Sacramento  
Bank: Left

### Type of Damage

Bank scour

### Total Length of Repair


125 feet (approximate)

### Repair Type

Rock fill, rock-soil mix,  
rock slope protection

### Lead Agency

Brannan-Andrus Levee  
Maintenance District



For further information,  
please contact:

**Elizabeth Scott**  
DWR Public Affairs Office  
(916) 835-5344  
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES  
PO Box 942836, Sacramento, CA 94236

[www levees.water.ca.gov](http://www levees.water.ca.gov)

