



Emergency Levee Repairs

Location

River: Bear River

River Mile: 1.2

Latitude/Longitude:

38.951479/-121.556837

Nearest Impact Area: Rio Oso

County: Sutter

Bank: Left

Type of Damage

Bank erosion

Length of Repair


1,200 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

Department of Water Resources



For further information,
please contact:

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www levees.water.ca.gov