



## Emergency Levee Repairs

### Location

River: Bear River

River Mile: 2.4

Latitude/Longitude:

38.957930/-121.547337

Nearest Impact Area: Rio Oso

County: Sutter

Bank: Left

### Type of Damage

Bank erosion

### Length of Repair

1,100 feet (approximate)

### Repair Type

Rock slope protection

### Lead Agency

Department of Water Resources



For further information,  
please contact:

**Elizabeth Scott**  
DWR Public Affairs Office  
(916) 835-5344  
[leveerepair@water.ca.gov](mailto:leveerepair@water.ca.gov)

DEPARTMENT OF WATER RESOURCES  
PO Box 942836, Sacramento, CA 94236

[www levees.water.ca.gov](http://www levees.water.ca.gov)