



Emergency Levee Repairs

Location

River: Cache Creek

Levee Mile: 4.2

Latitude/Longitude:

38.727202/-121.775781

Nearest Impact Area:

Woodland

County: Yolo

Bank: Left

Type of Damage

Bank erosion

Length of Repair

325 feet (approximate)

Repair Type

Setback levee

Lead Agency

Department of Water Resources

For further information,
please contact:

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov

