



DEPARTMENT OF
WATER RESOURCES

UPPER SACRAMENTO AREA *Fact Sheet* Site 141.4

Critical Levee Erosion Site

Emergency Levee Repairs

Location

River: Sacramento

River Mile: 141.4

Latitude/Longitude:

39.191261/-121.985448

Nearest Impact Area: Colusa

County: Colusa

Bank: Right

Type of Damage

Bank erosion

Length of Repair

2,350 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

Department of Water Resources



**For further information,
please contact:**

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www levees.water.ca.gov