



**US Army Corps
of Engineers®**

CENTRAL SACRAMENTO AREA *Fact Sheet* **Site 78.0**

Critical Levee Erosion Site

Emergency Levee Repairs

Location

River: Sacramento River

River Mile: 78.0

Latitude/Longitude:

38.769757/-121.595467

Nearest Impact Area:

Rio Linda/Pleasant Grove/
Verona

County: Sacramento

Bank: Left

Type of Damage

Bank erosion

Length of Repair



1,058 feet (approximate)

Repair Type

Rock slope Protection

Lead Agency

U.S. Army Corps of Engineers



**For further information,
please contact:**

Stan Wallin
Project Manager
U.S. Army Corps of Engineers
(916) 557-5225

Stan.J.Wallin@spk01.usace.army.mil