



## Emergency Levee Repairs

### Location

River: Sutter Slough

River Mile: 24.8

Latitude/Longitude:

38.295454/-121.60484

Nearest Impact Area:

Courtland

County: Sacramento

Bank: Left

### Type of Damage

Bank erosion

### Length of Repair



1,520 feet (approximate)

### Repair Type

Rock slope protection

### Lead Agency

Department of Water Resources



For further information,  
please contact:

**Elizabeth Scott**  
DWR Public Affairs Office  
(916) 835-5344  
[leveerepair@water.ca.gov](mailto:leveerepair@water.ca.gov)

DEPARTMENT OF WATER RESOURCES  
PO Box 942836, Sacramento, CA 94236

[www.levees.water.ca.gov](http://www.levees.water.ca.gov)