

Photographs of the Upper Jones Tract Levee Break in the Sacramento-San Joaquin Delta

June 3-6, 2004

Levee break and rushing water



Aerial view of the flood scene



End of the road (north end of the levee break looking southward)




End of the road



Water rushing through the Burlington Northern Sante Fe railroad trestle from Upper Jones Tract to Lower Jones Tract



Water rushing through the railroad trestle



Repairing the railroad tracks



A road no more



25-ton load of rip rap along the side of the built-up Trapper Slough levee



Piecing the road together again



High waters for farmers



Flooded farm buildings

