

Attachment 1

Timeline

SIGNIFICANT TIME EVENTS

Surveillance Video on February 7, 2007

Time	Event
10:30 a.m.	Video Begins
10:53 a.m.	Search using surveillance video begins
10:54 a.m.	Plant Operator arrives on deck
11:16 a.m.	SLFD Chief Engineer first noticed on deck. Based on Dive Tender reaction it appears SLFD Chief Engineer arrives at 11:12 a.m.
11:16 a.m.	SLFD Chief Engineer noticed making phone call
11:38 a.m.	SLFD Health and Safety Officer first noticed on deck
11:40 a.m.	SLFD Health and Safety Officer goes to dive van
11:46 a.m.	SLFD Chief first noticed on deck
12:14 p.m.	First Sheriff arrives
12:26 p.m.	SLFD Health and Safety Officer enters water
12:33 p.m.	Diver 2 recovered (Martin Alvarado)
12:41 p.m.	Diver 1 recovered (Tim Crawford)
12:46 p.m.	Excavator brought on deck
12:52 p.m.	Diver 1 removed from aqueduct
1:00 p.m.	Diver 2 removed from aqueduct
2:15 p.m.	Video ends

Dive Tender	Dark Shirt with Dark hat
Plant Operator	Greenish shirt with baseball cap
SLFD Chief Engineer	Dark vest over light-colored shirt with white hardhat
SLFD Health & Safety Officer	Dark Shirt. No hat.
SLFD Chief	Brown-tan coat, dark pants. No hat

Cellular Telephone Records

Time	Event
11:14 a.m.	SLFD Chief Engineer phone call to SLFD Health & Safety Officer

Area Control Center Logs

Time	Event
05:18 a.m	Units 2 and 3 unavailable – Scheduled outage
09:33 a.m	Ok issued to Crawford – Dive in front of Units 1, 2, 3 from 9:00 to 12:00
10:45 a.m	Senior Operator called by dive tender that bubbles from divers could not be located
10:50 a.m	Senior Operator attempts a call to SLFD Health & Safety Officer, but no answer
11:30 a.m	POC notified about the divers and request permission to vane down Unit 5 to minimum flow
11:31 a.m	Unit 5 flow decreased
11:49 a.m	Plant Operator calls Senior Operator to shut down Unit 5 per SLFD Chief
11:50 a.m	Unit 5 shut down