Exhibit H

Dive Report Summary

Dive Report Summary

Date of Dive	Dive Location	Purpose	Divers
2/5/07	**16L mile 132.81**	**Seal Stoplogs Install plugs**	**Tim Crawford Martin Alvarado**
1/8/07	18L mile 134.94	Check and Seal Gates	Tim Crawford Martin Alvarado
1/2/07	#75000081171 9L mile120.77 and #75000081172 11L mile124.18	Check and Seal Gates	Tim Crawford Martin Alvarado
12/26/06	14R mile 135.96	Check and Seal Gates	Tim Crawford Martin Alvarado
12/18/06	WWD 29R mile 167.84	Check and Seal Gates	Tim Crawford Martin Alvarado
12/11/06	16L mile 132.81	Check and Seal Gates	Tim Crawford Martin Alvarado
12/4/06	#75000080335 5L mile 111.93 and #75000080336 8L mile 117.5	Check and Seal Gates	Tim Crawford Martin Alvarado
11/28/06	**Dos Amigos Pumping Plant**	**Inspect Trashracks**	**Tim Crawford Martin Alvarado**
11/27/06	14L mile 130.85	Seal Gates	Tim Crawford Martin Alvarado
11/13/06	25R mile 160.45	Check and Seal Gates	Tim Crawford Martin Alvarado
11/7/06	90.14 Right Bank	Inspect for Damage	Tim Crawford Martin Alvarado
11/7/06	mile 88.5 Southside Pole Line 1 Bridge	Inspect for Damage	Tim Crawford Martin Alvarado
11/6/06	mile 89.5	Inspect Liner	Tim Crawford Martin Alvarado
11/1/06	mile 88.3	Check for Damage	Tim Crawford Martin Alvarado
10/30/06	20L mile 137.11	Check and Seal Gates	Tim Crawford Martin Alvarado
10/23/06	13L mile 129.88 and 17L mile 133.81	Seal Leaks	Tim Crawford Martin Alvarado
10/20/06	26L mile 147.02	Check and Seal Gates	Tim Crawford Martin Alvarado

Dive Report Summary

Date of Dive	Dive Location	Purpose	Divers
10/18/06	**Dos Amigos Unit 4**	**Install Cooling Water Intake Screen**	**Tim Crawford Dave Paulson**
10/16/06	15L mile 131.70	Check and Seal Gates	Tim Crawford Martin Alvarado
10/10/06	26R mile 161.60	Check and Seal Gates	Tim Crawford Martin Alvarado
9/18/06	20R mile 145.32	Check and Seal Gates	Tim Crawford Dave Paulson
9/18/06	19R mile 141.53	Check and Seal Gates	Tim Crawford Dave Paulson
8/14/06	35L mile 162.63	Check and Seal Gates	Tim Crawford Bill Collins
4/12/06	Gianneli Pumping Plant	Recover plates in front of plant	Tim Crawford James Ainslie
4/3/06	**Dos Amigos**	**Inspect Trashracks**	**Tim Crawford James Ainslie**
3/18/06	M.P. 79.02L	Dredge Canal Drain	Tim Crawford Pete Rigali
2/2/06	30R mile?	Check and Seal Gates	Tim Crawford James Ainslie
2/1/06	13L mile 129.88	Check and Seal Gates	Tim Crawford James Ainslie
1/12/06	#4 L mile 196.75	Seal Stoplogs	Tim Crawford James Ainslie
12/20/05	Edmonston	Inspect/Repair pipe for Domestic Water. 3" PVC pipe	Tim Crawford Dale Moisio
12/13/05	**Dos Amigos**	**Inspect Cooling Water Intakes**	**Tim Crawford James Ainslie**
10/26/05	ck 18	Inspect Domestic Water Pump Brackets	Tim Crawford James Ainslie
8/24/05	M.P. 77.11 R	Dredge Silt	Tim Crawford James Ainslie
6/30/05	?	Inspect Damaged Liner	Tim Crawford James Ainslie
6/28/05	?	Inspect Liner Damage	Tim Crawford James Ainslie

Dive Report Summary

Date of Dive	Dive Location	Purpose	Divers
6/9/05	M.P. 172.25 ck 20 1/2	Clean Flow Meters	Tim Crawford James Ainslie
5/25/06	Mile 66.37 ck 11 1/2	Install Flow Meter	Tim Crawford James Ainslie
5/12/05	Mile 155.64 ck 19	Inspect for Damage	Tim Crawford James Ainslie
5/11/05	**Banks Pumping Plant**	**Clean Cooling Water Strainers**	**Tim Crawford Dave Paulson Pat Whitlock**
5/9/05	M.P. 77.11 R	Inspect Turnout Gate	Tim Crawford James Ainslie
3/10/05	Delta Goodyear/Morrow/ M line gates	Inspect Gates	Tim Crawford James Ainslie
3/2/05	79.02	Inspect Gate and Canal Drain	Tim Crawford James Ainslie
1/24/05	23R mile 156.34 and 4L mile 110.52	Install Plug and Seal Gates	Tim Crawford James Ainslie
12/6/05	Delta Forebay Inlet Gate's	Check J Seals	Tim Crawford James Ainslie
1/5/05	Gianelli Pumping Plant	Pull Plug Out	Tim Crawford James Ainslie
12/17/04	156.34R (23R)	Remove Plug	Bill Collins Pete Rigali
12/13/04	M.P. 129.88 13L and 156.34 23R	Seal Gates and Stoplogs	Tim Crawford Pete Rigali
12/6/04	13R and 22R	(22R)Check and Seal Gates (13R) Install Plug & Seal Stoplogs	Tim Crawford James Ainslie Pete Rigali
12/3/04	Gianelli Pumping Plant	Install Plug	Tim Crawford Bill Collins
12/1/04	Gianelli Pumping Plant	Remove Plug	Tim Crawford James Ainslie
11/30/04	**Dos Amigos**	**Rig Grates for Grane**	**Tim Crawford James Ainslie Pete Rigali**
11/29/04	32L mile 158.47 and 25L mile 145.26	Set Stoplogs Seal Gates	Tim Crawford Pete Rigali
11/15/04	17R mile 139	Install Plug	Tim Crawford Bill Collins
11/12/04	27R mile 149.12	Remove Plug	Tim Crawford James Ainslie

Dive Report Summary

Date of Dive	Dive Location	Purpose	Divers
11/8/04	27R mile 149.12	Install Plug and Stoplog	Tim Crawford James Ainslie Bill Collins
?	ck 21 & ck 12 Transducers	Clean Transducers	Tim Crawford Bill Collins
11/1/04	36L mile 163.69	Seal Gates	Tim Crawford Bill Collins
10/25/04	M.P. 137. 15R and M.P. 128. 11R	Seal Stoplogs	Tim Crawford Bill Collins
10/18/04	27R mile 163.69	Seal Stoplogs	Tim Crawford Bill Collins
10/5/04	Gianelli Pumping Plant	Set Plug in Discharge Line	Tim Crawford Pete Rigali Bill Collins
10/4/04	Gianelli Pumping Plant #8	Install Plug Ring	Tim Crawford Bill Collins
10/4/04	**Dos Amigos**	**Trashracks**	**Tim Crawford Pete Rigali**
9/2/04	Middle River Grant Line Canal	Inspect Gates	Tim Crawford Pete Rigali
8/11/04	Sac. Deep Water Ship Channel	Retrieve Doppler From Location	Tim Crawford Dave Paulson
8/10/04	ck 21 and ck 11 ½ Flowmeters	Clean Flowmeters	Tim Crawford Pete Rigali
8/2/04	M.P. 9.34	Seal Stoplogs	Tim Crawford Bill Collins
7/27/04	M.P. 190. 23L	Seal Gates	Tim Crawford Bill Collins
7/26/04	Delta Clifton ct. Hyacinth Screens	Inspect and Reconnect Screens	Tim Crawford Dave Paulson
7/21/04	Sherman Island	Clean Fish Screens	Tim Crawford Dave Paulson
6/28/04	?	Clean fish Screens	Tim Crawford Ray Chavez
6/9/04	Sherman Island	Clean Moss and Inspect for Damage	Tim Crawford Pete Rigali
5/14/04	Mile 172.25 and 66.37 ck 11 ½ and 20 ½	Clean Flowmeters	Tim Crawford Bill Collins Pete Rigali

Dive Report Summary

Date of Dive	Dive Location	Purpose	Divers
5/4/04	7R mile 92.16	Seal Gates	Tim Crawford Pete Rigali
4/22/04	4R mile 82.10	Seal Gates	Tim Crawford Pete Rigali
4/21/04	3R mile 79.39	Check and Seal Gates	Tim Crawford Pete Rigali
4/7/04	Tom Payne slew	Inspect Flap Gates	Tim Crawford James Ainslie
4/7/04	M.P. 6.45	Inspect Liner	Tim Crawford James Ainslie
4/6/04	M.P. 241 Kern River Outlets	Seal Stoplog	Tim Crawford James Ainslie
3/22/04	2R mile?	Seal Gates	Tim Crawford Pete Rigali
3/18/04	M.P. 241 Kern River	Seal Stoplogs	Tim Crawford Pete Rigali James Ainslie
3/8/04	13R mile 133.81	Seal Gates	Tim Crawford Pete Rigali
3/4/04	Sherman Island	Inspect and Clean Fish Screens	Tim Crawford James Ainslie
3/2/04	Roaring River Outlet Gates	Inspect Flap Gates	Tim Crawford James Ainslie
2/25/04	Wheeler Ridge Pumping Plant Headworks	Seal Stoplogs	Tim Crawford Pete Rigali
2/19/04	Bacon Island Rock Slough	Recover Doppler Instruments	Tim Crawford James Ainslie
2/18/04	M.P. 241 Kern River Intake	Seal Stoplogs	Tim Crawford James Ainslie
2/4/04	Banks Intake Trashrack	Check for Debris Clean Cooling Intakes	Tim Crawford James Ainslie
1/27/04	?	Seal Gates	Tim Crawford Pete Rigali
12/23/03	CK 11 ½ mile 66.35	Clean and Inspect Stilling Well Pipes	Tim Crawford James Ainslie
12/17/03	36L M.P. 163.69L	Check and Seal Gates	Pete Rigali James Ainslie
12/16/03	15L mile 131.70	Remove Plug from Barrel	Tim Crawford James Ainslie
12/15/03	26L mile 147.02	Seal Gate	Tim Crawford James Ainslie

Dive Report Summary

Date of Dive	Dive Location	Purpose	Divers
12/11/03	Banks Pumping Plant # 10 and #11	Clear Intake of Debris	Tim Crawford James Ainslie
12/9/03	15L mile 131.7	Seal Stoplogs and Gate, Install Pipe Plug	Tim Crawford Pete Rigali
12/8/03	23L mile 140.57 18R mile 140.48	Check and Seal Gates	Tim Crawford Pete Rigali
12/2/03	9L mile 120.77	Check and Seal Gates	Tim Crawford James Ainslie
12/1/03	11L mile 124.18	Seal Stoplogs	Tim Crawford Pete Rigali
11/20/03	Beacon Island	Install Instruments	Tim Crawford Pete Rigali
11/17/03	28R mile 164.79	Check and Seal Gates	Tim Crawford Pete Rigali
11/10/03	16L mile 132.81 18L mile 134.9	Check and Seal Gates	Tim Crawford James Ainslie
11/4/03	Ck 10 ½ and Ck 20 ½ Transducers	Clean Flowmeters	Tim Crawford Bill Collins Pete Rigali
11/3/03	5L mile 111.93 and 8L mile 117.5	Check and Seal Gates	Tim Crawford James Ainslie
10/27/03	14L mile 130.85	Check and Seal Gates	Tim Crawford Pete Rigali
10/14/03	14R mile 135.96	Check and Seal Gates	Pete Rigali James Ainslie
10/7/03	Beacon Island	Deploy Doppler	Tim Crawford James Ainslie
10/6/03	Mile 137.11	Check and Seal Gates	Tim Crawford Pete Rigali
9/29/03	Calif. Aqueduct 17L mile 133.81	Check and Seal Gates	James Ainslie Pete Rigali Leroy Lindo(Tender)
9/29/03	Delta Hyacinth Screen	Inspect Screen	Tim Crawford Pat Whitlock
9/22/03	15L mile 131.7	Check and Seal Gates	Tim Crawford Pete Rigali
9/15/03	13L mile 129.88 Westlands	Check and Seal	Tim Crawford James Ainslie
9/15/03	26R mile 161.6 Westlands	Seal Gate	Tim Crawford Pete Rigali
8/12/03	Delta North Bay	Inspect Gate	Tim Crawford James Ainslie
7/7/03	Beacon Island, Delta	Retrieve YSI Instrument	Tim Crawford Pete Rigali

Dive Report Summary

Date of Dive	Dive Location	Purpose	Divers
6/26/03	Joaquin River, Patterson, CA	Clear Debris from Piers for Flow Measurement Equip	Tim Crawford James Ainslie
6/24/03	Delta, Montazuma Gates	Inspect Flap Gates	Tim Crawford James Ainslie
5/22/03	Sherman Island, Delta	Clean and Inspect Fish Screens #1 thru #13	Tim Crawford James Ainslie
3/20/03	Mile 90.1	Photograph Damage and Release Die	Tim Crawford James Ainslie
3/19/03	Sherman Island Fish Screens #6 thru #13	Clean and Inspect Screens	Tim Crawford James Ainslie
3/18/03	Mile 90.18	Look for Leak	Tim Crawford James Ainslie
3/18/03	19R mile 141.53	Check and Seal Gates	Tim Crawford James Ainslie
3/17/03	20R mile 145.32	Seal Gates	Tim Crawford James Ainslie
3/10/03	29R mile 167.84	Seal Gates	Tim Crawford James Ainslie
3/6/07 and 3/7/03	Sherman Island Fish Screens	Assist. C.M. to Remove Fish Screens	Tim Crawford Pat Whitlock
3/3/03	30R mile 171.51	Seal Gates	Tim Crawford James Ainslie
2/26/03	13R, 22L, 34L, 28R	Measure Trashracks	Tim Crawford James Ainslie
2/4/03	**Dos Amigos Pumping Pump**	**Assist Grane**	**Tim Crawford Bill Collins**
2/3/03	3R mile 108.46	Seal Stoplogs	Tim Crawford Bill Collins
1/29/03	4L mile 196.75	Seal Stoplogs	Tim Crawford James Ainslie
1/9/03	7L mile 115.43	Check and Seal Gates	Tim Crawford James Ainslie
1/13/03	19L mile 136.05 21L mile 138.29	Check and Seal Gates	Tim Crawford James Ainslie
1/10/03	Delta, Beacon Island	Install Flow Instruments	Tim Crawford James Ainslie

Dive Report Summary

Date of Dive	Dive Location	Purpose	Divers
1/6/03	6L mile 115.43	Seal Gates	Tim Crawford James Ainslie
12/18/02	8 Mile Road, Stockton	Look for Leak	Tim Crawford James Ainslie
12/16/02	12L mile 126.65	Check and Seal Gates	Tim Crawford James Ainslie
12/16/02	10L mile 121.92	Check and Seal Gates	Tim Crawford James Ainslie
12/13/02	8 Mile Road, Stockton	Look for Leak in Levee	Tim Crawford James Ainslie
12/9/02	12R mile 132.74	Seal Gates	Tim Crawford James Ainslie
12/9/02	34L mile 161.6	Seal Gates	Tim Crawford James Ainslie
12/2/02	13L mile 129.88	Seal Gates and Measure Silt	Tim Crawford James Ainslie
11/18/02	28L mile 150.88	Seal Gates, Inspect cond. of Gates, Measure Silt	Tim Crawford James Ainslie
11/5/02	1R mile 104.18 Westlands	Seal Gates Inspect Cond. of Gates, Measure Silt	Tim Crawford James Ainslie
10/31/02	Delta, Holland Marine Area	Install Water Quality Instruments and Flow Measurement Instruments	Tim Crawford James Ainslie
10/28/02	29L mile 152.35	Seal Gates Survey Silt	Tim Crawford James Ainslie
10/22/02	Gianelli Pumping Plant # 8	Locate Discharge Line to install Pig. Pig was wrong size	Tim Crawford James Ainslie
10/23/02	Montazuma Slough Boat Lock, North Bay Delta	Clean Stoplogs slots and Assist. Grane with lifting cables	Tim Crawford James Ainslie
10/21/02	35L mile 162.63 Westlands	Seal Gates Inspect and Survey Silt	Tim Crawford James Ainslie