



AMERICAN LEAK DETECTION

THE ORIGINAL LEAK SPECIALISTS™

Ph (909) 820-6555 Fx (760) 320-9319
www.americanleakdetection.com

REMIT TO:
American Leak Detection
PO Box 1701, Palm Springs, CA
92263

INVOICE

| | | |
|-------------------|---------------------|------------------------|
| DUE DATE | Invoice Date | INVOICE # |
| 11/28/2014 | 10/29/2014 | 11535 |
| Start Date | | Completion Date |
| 10/27/2014 | | 10/29/2014 |

| | |
|---|--|
| Billing Address | Site Address |
| Terrace Water Company, INC. P.O. Box 640 Colton, CA 92324 | Terrace Water Company 1095 1/2 Stevenson Street Colton, CA 92324 |

| | | | |
|----------------------|------------------------|-------------------|------------------------|
| Claim#/P.O. # | Tech | Order Date | Referral |
| | RMDB | 10/24/2014 | CRWA |
| Billing Fax # | Billing Phone # | | Site Phone #(s) |
| | 909-838-0291 | | 909-825-5224 |

| Item | Work Description | Amount |
|------|--|----------|
| MCLS | <p>Municipal Correlator/Leak Survey</p> <p>A full survey was performed on the Terrace Water Company's distribution system. Based on maps provided by the company and the assistance of their technician Luis, we went through the system checking each isolation valve, air release valve, hydrant, and stop valves by making direct contact with listening devices and survey tools. All points checked were marked on the maps provided and any noise heard indicated by number on the maps at the points they were found. Half of the system was checked on the first day and the other half was completed on the second. Two areas of concern for underground leaks were noticed but upon returning on the third day these areas were found to be quiet and the noise created was due to consumption by customers and a leak was not present. Both sections were correlated to insure no problems were present. A residential property was checked as well to locate a leak on the irrigation supply system in the backyard, and help to determine if the neighboring property which is supplied by a different water department was illegally hooked up to Terrace Water by tying into the plumbing system on the property that was checked. Results showed that the neighboring property is indeed stealing water. Another property was checked to determine how the area was supplied with water as it is not hooked up to a meter on the system. Due to the type of piping, the line could not be properly located and no determination was made. The maps provided will show the results of the survey along with a listing of the problems located and what they entail. Three days were spent detecting the issues on the system.</p> <p>1. Small leak on hydrant - visible - Cypress Ave and Valley Blvd</p> | 3,900.00 |

GUARANTEE ON DETECTIONS: All leak detection work is guaranteed for 30 days from the date of completion. In the event the leak is NOT where marked, customer will NEED to NOTIFY ALD within the 30 day period of guarantee in order to RECEIVE A FREE RE-TEST or to determine if a REFUND IS VALID (all refunds are at SOLE DISCRETION of ALD). ALD will not be liable for any consequential losses.

| |
|---------------------|
| Total: |
| Balance Due: |
| Net 30 days |

GUARANTEE ON REPAIRS: Minor repairs made by American Leak Detection are guaranteed for 30 days. Major repairs are guaranteed for 1 year. All repairs are guaranteed from date of completion and for defective workmanship only.

NOTE: Additional leaks may be present on this line. The identified leak must be REPAIRED before additional leaks can be located. Repairs performed by American Leak Detection include re-testing the system for further leaks at the time of the completed repair. If requested to test repairs performed by others, a fee of \$175 per hour will apply.

Contractors are required by law to be licensed and regulated by the Contractor's State License Board. Any questions concerning a contractor may be referred to the Registrar, Contractors State License Board, 9835 Goethe Road, Sacramento, CA 95827. Mailing Address: P.O. Box 26000, Sacramento, CA 95826.

I authorize American Leak Detection to complete the above-described work and agree to the charges and terms as described. I further agree to pay reasonable charges for collection, including attorney's fees, court fees, and collection costs, in the event of my default, as well as penalty interest as allowed by law.

SIGNATURE: _____

DATE: _____

**State of California
Contractor Lic# 527380
Federal ID# 33-0106141**



AMERICAN LEAK DETECTION

THE ORIGINAL LEAK SPECIALISTS™

Ph (909) 820-6555 Fx (760) 320-9319
www.americanleakdetection.com

REMIT TO:
American Leak Detection
PO Box 1701, Palm Springs, CA
92263

INVOICE

| | | |
|-------------------|---------------------|------------------------|
| DUE DATE | Invoice Date | INVOICE # |
| 11/28/2014 | 10/29/2014 | 11535 |
| Start Date | | Completion Date |
| 10/27/2014 | | 10/29/2014 |

| Billing Address | Site Address |
|---|--|
| Terrace Water Company, INC. P.O. Box 640 Colton, CA 92324 | Terrace Water Company 1095 1/2 Stevenson Street Colton, CA 92324 |

| Claim#/P.O. # | Tech | Order Date | Referral |
|---------------|-----------------|-----------------|----------|
| | RMDB | 10/24/2014 | CRWA |
| Billing Fax # | Billing Phone # | Site Phone #(s) | |
| | 909-838-0291 | 909-825-5224 | |

| Item | Work Description | Amount |
|------|--|--------|
| | 2. Small leak on south isolation valve - valve can full of water and generating noise - Cypress Ave and H Street 3. Leak between isolation valve and hydrant - underground - H Street and Kelly Lane 4. Leaking valve stem isolation - visible and generating small amount of noise - Rancho Avenue and Olive Avenue 5. Leaking isolation valve for hydrant - large wet area surrounding valve can - Cypress Avenue between Olive Avenue and C Street 6. Leaking isolation valve - valve can full of water and generating small amount of noise Rancho Avenue and Stevenson Street 7. Hydrant that was inaccessible - end of Stevenson Street behind gate in yard 8. Isolation valve that was un-located | |

GUARANTEE ON DETECTIONS: All leak detection work is guaranteed for 30 days from the date of completion. In the event the leak is NOT where marked, customer will NEED to NOTIFY ALD within the 30 day period of guarantee in order to RECEIVE A FREE RE-TEST or to determine if a REFUND IS VALID (all refunds are at SOLE DISCRETION of ALD). ALD will not be liable for any consequential losses.

| | |
|---------------------|-------------------|
| Total: | \$3,900.00 |
| Balance Due: | \$3,900.00 |
| | Net 30 days |

GUARANTEE ON REPAIRS: Minor repairs made by American Leak Detection are guaranteed for 30 days. Major repairs are guaranteed for 1 year. All repairs are guaranteed from date of completion and for defective workmanship only.

NOTE: Additional leaks may be present on this line. The identified leak must be REPAIRED before additional leaks can be located. Repairs performed by American Leak Detection include re-testing the system for further leaks at the time of the completed repair. If requested to test repairs performed by others, a fee of \$175 per hour will apply.

Contractors are required by law to be licensed and regulated by the Contractor's State License Board. Any questions concerning a contractor may be referred to the Registrar, Contractors State License Board, 9835 Goethe Road, Sacramento, CA 95827. Mailing Address: P.O. Box 26000, Sacramento, CA 95826.

I authorize American Leak Detection to complete the above-described work and agree to the charges and terms as described. I further agree to pay reasonable charges for collection, including attorney's fees, court fees, and collection costs, in the event of my default, as well as penalty interest as allowed by law.

SIGNATURE: _____

DATE: _____

State of California
Contractor Lic# 527380
Federal ID# 33-0106141